

m 7/5

Lamont - Doherty Geological Observatory | Palisades, N.Y. 10964  
of Columbia University

Cable: LAMONT, Palisades, New York State

Telephone: Code 914, Elmwood 9-2900

TWA: 710-576-2653

CRUISE REPORT

Ship Name: VEMA

Cruise No: 35-02

Departure: March 9, 1978 from Port Victoria, Seychelles  
Date Port

Arrival: April 6, 1978 at Colombo, Sri Lanka  
Date Port

Days at Sea: 28

Days Foreign Port: 3

No. of days in arrival port

Area of Operation:

Somali Basin, Gulf of Aden, Arabian Sea.


Program Description:

See Attached.

Participants: (All L-DGO unless otherwise specified)

James Cochran	Chief Scientist
William Van Steveninck	Heat Flow
Brian Mossman	E.T.
Dwight Mossman	E.T.
Brian Ostrowski	E.T.
Jeff Schwartz	Core Describer
Hector Smith	Air Gunner

All inquiries regarding cruise should be made to the chief scientist.



- KEY:**
- S-2 - D-1A
  - S-3 - MG-1
  - S-4 - MG-2
  - S-5 - MG-3
  - S-6 - MG-4
  - S-7 - MG-5
  - S-8 - MG-6
  - S-9 - MG-7
  - S-10 - MG-8
  - S-11 - C-2
  - S-12 - C-3
  - S-13 - C-4
- Sonobuoy 1 to 24
- \* INTENSIVE RESEARCH
- SHADE AREA

Program Description: The main objective of this cruise was a study of the continental margins of the Gulf of Aden. The work was concentrated in the northern half of the Gulf of Aden because we did not have permission from Somalia to enter their waters and also because a war was going on in Somalia and Ethiopia. Roughly 20 lines were run at about 10 mile spacings from the Sheba ridge flank (many of them actually went to the ridge crest) across the magnetic quiet zone to 20 miles off shore. We were able to document the presence of a magnetic quiet zone and to trace changes in the nature of the quiet zone and quiet zone-ridge flank boundary along strike. We were only able to get a hint of the structures on the landward side of the quiet zone due to having to turn around 20 miles offshore. That point was usually at about 600 fms depth on the continental slope. Roughly 20 sonobuoys were run and basement arrivals recorded on most of them. Preliminary analysis shows oceanic type velocities under the magnetic quiet zone.

In general the equipment worked quite well. The exception was the 12 KC P.D.R. which gave a very dirty record. The profilers were noisy during the first week or so of the cruise, but were generally fairly quiet after that. We did have trouble with sharks slashing at the equipment. They completely destroyed two eel sections and the air gun hoses were constantly being cut. Another source of great frustration is ship generated noise, primarily from the radio and electric paint chippers, but we even got interference from an electric drill operated in the wet lab.

They saw

Telephone: Code 914, Elmwood 9-2900

TWX-710-576-2653

## CRUISE REPORT

Ship name: VEMA Cruise No. 35-03  
Departure: April 9, 1978 from Colombo, Sri Lanka  
Arrival: April 16, 1978 at Singapore  
Days at sea: eight plus additional day at anchorage  
Days foreign port: dry dock and extended port stay  
Area of operation: Bay of Bengal, Strait of Malacca  
Program Description: IN TRANSIT from Sri Lanka to Singapore  
Participants (L-DGO personnel)

Mossman, Brian	E.T.
Mossman, Dwight	E.T.
Ostrowski, Brian	E.T.
Schwartz, Jeffrey	Core Describer
Van Steveninck, William	Heat Flow (party chief)

All inquiries regarding cruise should be made to the party chief.

Being an "IN TRANSIT" leg, V35-03 was mostly concerned with getting from here to there; viz., Colombo, Sri Lanka to Singapore. It did, however, provide some time to examine certain aspects of the equipment used in collecting the underway data. In view of the harshness of the seagoing environment and the impartiality of the second law of thermodynamics, it may be stated at the outset that it is remarkable that the equipment aboard the ships functions as well as it does and for the extended periods of constant operation demanded in this type of service.

One very serious problem is the lack of documentation available to the shipboard E.T. The worst case in point is the manual which accompanies the profiler. Not only is the information it contains conflicting and incomplete, but the format used to describe the various modi operandi of the unit is haphazard and confusing. It is of little value when troubleshooting the equipment—when time is of the essence. In this situation, the E.T. must rely completely on his personal experience with the unit. Unfortunately, when the ship is underway and the equipment is running, it cannot be extricated from its primary role of collecting data; so the E.T. has no hands-on experience with the unit until something goes wrong— a bad time for on-the-job training.

For the same reason, spare modules often cannot be repaired after they have been removed from a piece of equipment. A backup unit would alleviate the above conditions but would be expensive. The only alternative is to give the E.T.'s some time with the equipment when the data is not critical. Vema 35-03 provided


a good opportunity for some of these activities to take place.

Another glaring weakness in documentation was in evidence as regards changes or modifications made to equipment. There is little or no indication of when and where such changes are made and for what reasons. The packet of diagrams for the gravity computer, for example, contained three or four conflicting schematics which gave no indication as to which drawing actually was a faithful representation of the system in use. Several sheets were clearly marked 'Conrad.' Another case in point was the 3.5 KHz P.D.R. To my knowledge, there is no indication anywhere that the input board must be modified to accomodate the higher signal level coming out of the newer transceivers. For this very reason, the records for V 35-01 and V 35-02 were of marginal quality. Many man hours were wasted in attempting to fix the 3.5 when the whole problem was lack of documentation. The E.T.'s have started a log for each piece of equipment. This should keep track of what has been done recently; but what was done three years ago may be expected to lead to surprises for years to come.

In addition, people seem to have gotten sloppy over the years. Many of the precision resistors in the profiler modules have been replaced by carbon resistors. In addition to being "noisy," these resistors simply do not have the close tolerance necessary to insure that the gain of the amplifiers will have any more than a casual relationship to the settings on the dials. This reflects the attitude of complacency which has become evident in the testing procedures for most Lamont equipment. There is only very sketchy

information available concerning what signals to expect both on the input and from the output of our in-house equipment. It has been "good enough" when a signal is present at the output, irrespective of the signal level required at the input to drive the output to a reasonable level.

During the leg, I did some work on the eel preamplifiers both in the eel itself and in the upper lab. These experiments were aimed at using a balanced line to transmit the signal from the eel back to the ship. The results raise some serious questions concerning the assumptions made in designing the eel preamp currently in use. While my design had vastly better common mode rejection of radio interference generated by the ship's transmitters, preliminary results seemed to indicate that the actual signal was not significantly improved. While we may safely conclude therefore that these conceptual blunders did not adversely affect the performance of the eel under actual operating conditions, it is nevertheless frightening to think that this result may have been fortuitous.

A handwritten signature in dark ink, appearing to read 'William Van Steveninck', with a stylized flourish at the end.

William Van Steveninck

Party Chief, VEMA 35-03