

MGL1905 Seismic Configuration by sequence acquired with offsets

DR Table #	Sequence	line name	Shot spacing (m)	number of active channels	sample rate	record length	source sub-array used	source depth	streamer depth	NRP-COS	COS-CNG	comment
	001	MGL1905P1004	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	002	MGL1905P1116	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	003	MGL1905P1012	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Port main engine failure, line terminated early
	004	MGL1905P1124	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	005	MGL1905P1020	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	006	MGL1905P1132	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	007	MGL1905P1028	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	008	MGL1905P1140	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	009	MGL1905P1036	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	010	MGL1905P1148	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	011	MGL1905P1044	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	012	MGL1905P1156	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Gun controller failed @ SOL, some missed shots reconfiguring spare
	013	MGL1905P1052	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Spectra GPS issue @ SOL, restart spectra and spectra hardware
	014	MGL1905P1164	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	015	MGL1905P1060	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	016	MGL1905P1172	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	017	MGL1905P1068	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Streamer 1 failed during line
	018	MGL1905P1076	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Multiples streamer 4 failures during line
	019	MGL1905P1180	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	020	MGL1905P1084	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	021	MGL1905P1188	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	022	MGL1905P1092	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	023	MGL1905P1188	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 failing again, multiple channel dropouts
	024	MGL1905P1092	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 failing, multiple channel dropouts
	025	MGL1905P1100	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Gun controller rebooted online some missed shots
	026	MGL1905P1196	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	027	MGL1905P1108	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	Gun controller rebooted online some missed shots
	028	MGL1905P1204	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	029	MGL1905P1076	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	030	MGL1905P1124	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	031	MGL1905P1060	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	032	MGL1905P1212	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	033	MGL1905P1100	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	034	MGL1905P1220	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	035	MGL1905P1348	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	036	MGL1905P1228	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	037	MGL1905P1356	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	038	MGL1905P1236	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	039	MGL1905P1364	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	040	MGL1905P1244	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	041	MGL1905P1372	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	042	MGL1905P1252	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	PSO shutdown during line
	043	MGL1905P1380	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	044	MGL1905P1260	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	045	MGL1905P1388	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	046	MGL1905P1268	37.5	1872	2	12	1&2 / 3&4	12	16	280	175	
	047	MGL1905P1396	37.5	1872/1404	2	12	1&2 / 3&4	12	16	280	175	streamer 4 partially failed
	048	MGL1905P1276	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	049	MGL1905P1284	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording

	050	MGL1905P1404	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording / PSO shutdown during line
	051	MGL1905P1292	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	052	MGL1905P1412	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	053	MGL1905I1292	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording, Spectra shot numbering 80 shots off from preplot
	054	MGL1905I1412	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	055	MGL1905P1300	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	056	MGL1905P1420	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	057	MGL1905P1308	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	058	MGL1905P1428	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	059	MGL1905P1316	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	060	MGL1905P1436	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	061	MGL1905R1284	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	062	MGL1905I1348	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	063	MGL1905I1252	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	064	MGL1905A1348	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	065	MGL1905P1324	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	066	MGL1905B1348	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	067	MGL1905R1324	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
	068	MGL1905C1348	37.5	1404	2	12	1&2 / 3&4	12	16	280	175	Streamer 4 completely failed, no channels recording
												End of 3D acquisition
												Start of 2D acquisition
	069	MGL1905P2007	37.5	936	2	14	All	12	16	230	189.7	Line aborted d/t issues with record length and shooting speed
	070	MGL1905B2007	37.5	936	2	12	All	12	16	230	189.7	
	071	MGL1905P2008	37.5	936	2	12	All	12	16	230	189.7	
	072	MGL1905P2009	37.5	936	2	12	All	12	16	230	189.7	
	073	MGL1905P2006	37.5	936	2	12	All	12	16	230	189.7	
	074	MGL1905P2004	37.5	936	2	12	All	12	16	230	189.7	
	075	MGL1905P2005	37.5	936	2	12	All	12	16	230	189.7	
	076	MGL1905P2003	37.5	936	2	12	All	12	16	230	189.7	
	077	MGL1905P2002	37.5	936	2	12	All	12	16	230	189.7	
	078	MGL1905P2001	37.5	936	2	12	All	12	16	230	189.7	
												End of Survey