

— 1908Z - 1 Feb 1977
50395 FND1623-3

1830Z 50426

1815Z C/K291° -

1803Z c/c 289°

1800Z 50449

291° 10.5 kts 1 Feb 77

1734Z c/c 291°

1730Z 50450 29

1707Z c/c 293°

1700Z 50431

294° 10.5 kts 1 Feb 77

1630z 5038 294° 10.5 kts 1637

1600z 50350 295° 10.5 kts

1606z

c/c 294°

c/c 295° 1536z

1530z 50325 296° 10.5 kts

1507 Z c/c 296°

1500Z 50315 298 10.5 kts 1 FEB 77

1436 Z c/c 298°

1430Z 50300 296° 10.5 Kts 1 FEB 77

1406Z C/C 296°

1400Z 294° 10kts

50280

1 Feb 77

1347Z C/C 294°

50254

1330Z 1 Feb 77 293°

@ 10kts

50224

1300Z 1 Feb 77 293° @ 10kts

1230Z 1 Feb 77 293° @ 10 kts. 50182

1200Z 1 Feb 77

I4 23-3

293° @ 10 kts

50167

1130 Z 1 Feb 77

I4 23-3

293° @ 10 kts

covered
well

≈ 28° 30.6' N

-92° 36.9' W

1103 Z c/c 293°

1100 Z 1 Feb 77

I4 23-3

290° @ 10 kts

1030 Z 1 Feb 77

I4 23-3

290° @ 10 kts

50170

50182

50191

1000Z 290° @ 10.5 kts
50168

0951Z c/c 290°

0930Z 274° 50143 10.5 kts

274°
c/c 0905Z

0900Z 270° 10.5 kts 50138 1 FEB 77

0830Z 50146 277° 10kts 1 FEB 77

0800Z 50156 277° 10kts 1 FEB 77

0730Z 50159 277° 10kts

0700Z 50157 277° 10 kts 1 Feb 77

0636Z c/c 277°

0630Z 50152
274° @ 10 Kts.

410 270° 05082

0600Z 50150

1 Feb 77 272° 10 kts

0533Z 410 272°

0530Z 50162

269° @ 10 Kts

WARNING
5 FEET TO END OF CHART

0500Z 50180 269° 10 kts

1 Feb 77

1449Z C/C 269°

0430Z 50164 10kts 265° 1 Feb 77

50139

0400Z 265° 10kts 1 Feb 77

0330Z

260° 10kts

1 FEB 77

0323Z

c/c 260°

0315Z c/c 280°

0307Z c/c 276°

0300Z

273° 10kts 50180

1 FEB 77

1 FEB 77

0230Z

273° 10kts

50193

0204Z. C/K 273°

50198. 0200Z. 1 Feb 77. 255° @ 10Kb.

50223 0130Z. 1 Feb 77. 255° @ 10Kb.

50256
0100Z. 1 Feb 77. 255°
@ 10Kb.

0030 Z 1 Feb 77

I4 23-3

255° @ 10 kts

50275

0002 Z. C/C 255°

50290

X 0000 Z. 1 Feb. 77. 252° @ 10 kts.

2330Z 31 JAN 77. 252° @ 10 Kts.

50292

2322Z 31 JAN 77

50292

IG 23-3

252° @ 10 kts

31 I 77

IG 23-3

