

## MGL2411 Seismic Configuration by sequence acquired with offsets

DR Table #	Sequence	line name	Shot spacing (m)	Number of active channels	sample rate	record length	source sub-array used	source depth	streamer depth	NRP-COS	COS-CNG	Comment
1	001	MGL2411001SNP1	50	1200	2	20	4 Arrays used	12	12	276	178.2	Early End of Line because of S3G8 Autofire
2	002	MGL2411002SNP2	50	1200	2	20	4 Arrays used	12	12	276	178.2	S3G7 disabled after SP 4227, S2G1 started autofiring after SP 4750
3	003	MGL2411003D01P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	Early end of line to troubleshoot streamer telemetry
2	004	MGL2411004D03P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	Possible cable strike caused last 5 birds to lose comms
2	005	MGL2411005T45P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	006	MGL2411006D05BP1	50	1200	2	20	4 Arrays used	12	12	276	178.2	No guns firing because of alarm from compressor SP 11136-11140
2	007	MGL2411007T56P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	008	MGL2411008D06P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	009	MGL2411009T67P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	Incomplete shots/files because of telemetry failure
2	010	MGL2411010D07BP1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	011	MGL2411011T78P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	012	MGL2411012D08P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	Several shots with missing traces because of looped telemetry
2	013	MGL2411013T89P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	014	MGL2411014D09P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	015	MGL2411015T910P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	016	MGL2411016D10P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	017	MGL2411017T1011A	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	018	MGL2411018D11P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	019	MGL2411019T1112	50	1200	2	20	4 Arrays used	12	12	276	178.2	Line aborted after engine failure and loss of power
2	020	MGL2411020D13P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	Array 3 disabled for recovery after SP 31276
2	021	MGL2411021T1312	50	1200	2	20	4 Arrays used	12	12	276	178.2	Array 3 disabled and onboard at start of line
2	022	MGL2411022D12P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	023	MGL2411023SSEP1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	024	MGL2411024SSWP1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	025	MGL2411025D06P2	50	1200	2	20	4 Arrays used	12	12	276	178.2	Disabled strings 1 & 2 @ SP 41365 due leadin entanglement
2	026	MGL2411026T56P2	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	027	MGL2411027D05BP2	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	028	MGL2411028T56BP1	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	029	MGL2411029D06P3	50	1200	2	20	4 Arrays used	12	12	276	178.2	
2	030	MGL2411030T62P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	Array 3 disabled for repair SP 48252-48405
2	031	MGL2411031D02P1	50	1200	2	20	4 Arrays used	12	12	276	178.2	S2G4 disabled after SP 51196
4	032	MGL2411032T23BP1	50	1200	2	20	4 Arrays used	12	12	276	178.2	S2G4 disabled, S3G8 disabled after SP 53117
5	033	MGL2411033TEST	50	1200	2	20	4 Arrays used	12	12	276	178.2	Test line to test first arrivals NTBP