

The Knudsen 4 kHz sub-bottom profiler on Kilo Moana cruise KM0503 did not work satisfactorily. It provided no usable data except when stopped on station.

CTD data were obtained in the last 6 hours onsite, but the OBS did not work. The goal for the casts was turbidity which was not captured.